



Photo 1 Coppice regrowth and mulched slash material, April 2004.



Photo 2 Damage to roadway at the Timewell Road WWTP following extreme rainfall, April 2004



Photo 3 2004 harvest(foreground) & coppice regrowth from 2003 harvest (background), July 2004



Photo 4 Main irrigation storage dam at commencement of overflow, July 2005



Photo 5 Main irrigation storage dam at one-third capacity, March 2006



Photo 6 Timewell Road WWTP upgrade works, June 2006